

Bauxite

Art. ID NCS DC14221
Unit 50 g
Deliverydetails No Dangerous Good /not restricted

Text/Information	Analyte/Parameter	CAS number	Concentration/Value	Unit	Method	Source
	SiO ₂		10,07 ± 0,07	%		
	Al ₂ O ₃		83,61 ± 0,13	%		
	Fe ₂ O ₃		1,71 ± 0,01	%		
	CaO		0,45 ± 0,03	%		
	MgO	[1309-48-4]	0,18 ± 0,02	%		
	K ₂ O		0,2 ± 0,01	%		
	Na ₂ O		0,036 ± 0,004	%		
	TiO ₂		3,27 ± 0,06	%		
	P ₂ O ₅		0,22 ± 0,05	%		
	Loss on Ignition (L.O.I)		0,098 ± 0,007	%		