

Coal - Ash, CRM, Fusibility of Coal Ash

Art. ID NCS FS28001
Unit 5 g (powder)
Deliverydetails No Dangerous Good /not restricted

Text/Information	Analyte/Parameter	CAS number	Concentration/Value	Unit	Method	Source
Mildly reducing atmosphere	Deformation temperature		1161	Fusibility (°C)		
Mildly reducing atmosphere	Softening temperature		1190	Fusibility (°C)		
Mildly reducing atmosphere	Hemisphering temperature		1198	Fusibility (°C)		
Mildly reducing atmosphere	Fluid temperature		1204	Fusibility (°C)		
Oxidizing atmosphere	Deformation temperature		1211	Fusibility (°C)		
Oxidizing atmosphere	Softening temperature		1230	Fusibility (°C)		
Oxidizing atmosphere	Hemisphering temperature		1239	Fusibility (°C)		
Oxidizing atmosphere	Fluid temperature		1252	Fusibility (°C)		