

Coal - Ash, CRM, Fusibility of Coal Ash

Art. ID NCS FS28002
Unit 5 g (powder)
Deliverydetails No Dangerous Good /not restricted

Text/Information	Analyte/Parameter	CAS number	Concentration/Value	Unit	Method	Source
Mildly reducing atmosphere	Deformation temperature		1217	Fusibility (°C)		
Mildly reducing atmosphere	Softening temperature		1340	Fusibility (°C)		
Mildly reducing atmosphere	Hemisphering temperature		1357	Fusibility (°C)		
Mildly reducing atmosphere	Fluid temperature		1369	Fusibility (°C)		
Oxidizing atmosphere	Deformation temperature		1356	Fusibility (°C)		
Oxidizing atmosphere	Softening temperature		1408	Fusibility (°C)		
Oxidizing atmosphere	Hemisphering temperature		1420	Fusibility (°C)		
Oxidizing atmosphere	Fluid temperature		1445	Fusibility (°C)		