

*****sold out***see new batch FAPAS-FCCM7-CCP42QC-T07419QC***Heavy Metals in Powdered Rice Quality Control Material**

Art. ID FAPAS-FCCM7-CCP42QC-T07352QC
Unit 50 g
Deliverydetails No Dangerous Good /not restricted

Description

Surplus test materials from PT may be available for purchase as quality control (QC) samples. These QC samples may be used for troubleshooting poor performance in the PT, training of new staff, method development or generating QC charts. Fapas QCs have an associated datasheet which provides the same data of assigned values and performance limits as in the PT.
 Uses and properties of Quality Control (QC) samples:
 Troubleshoot PT performance
 Generate control charts
 Training staff
 Provide laboratory performance limits under normal parameters
 Stability estimated for short-term use

Text/Information	Analyte/Parameter	CAS number	Concentration/Value	Unit	Method	Source
	Arsenic (As) (inorganic)		96-235	µg/kg		
	Arsenic (As) total		126-296	µg/kg		
	Cadmium (Cd)	[7440-43-9]	53,8-138,4	µg/kg		
	Lead (Pb)	[7439-92-1]	179-403	µg/kg		
	Mercury (Hg) total		59-153	µg/kg		