

Histat-50 Reference Standard, Curie point

Art. ID PE-09988019
Unit each
Deliverydetails ADR Limited Quantity (LQ) / AIR Dangerous Good (DG) /not restricted

Text/Information	Analyte/Parameter	CAS number	Concentration/Value	Unit	Method	Source
	Curie point		1000	°C		