

Graphite

Art. ID NCS DC28120
 Unit 50 g
 Deliverydetails No Dangerous Good /not restricted

Description

Ad, Vd: GB2122?2008 analytical method of coal for industry, GB/T3521-2008 Chemical analysis method of graphite. // SiO₂: Gravimetric method after dehydration with perchloric acid, Molybdenum blue photometric method // Fe₂O₃: EDTA titrimetric method after separation, Photometric method after separation, ICP-AES // CaO: EDTA titrimetric method, ICP-AES method, AAS // MgO: Atomic absorption spectrometry, ICP-AES method, EDTA titrimetric method, // Al₂O₃: EDTA titrimetric method, ICP-AES // TiO₂: ICP-AES method, Colorimetric method with dianisopyrylmethane, H₂O₂ photometric method // MnO: ICP-AES method, Atomic absorption spectrometry // K₂O: ICP-AES method, Atomic absorption spectrometry // Na₂O: ICP-AES method, Atomic absorption spectrometry // P₂O₅: Molybdenum blue photometric method, ICP-AES

Text/Information	Analyte/Parameter	CAS number	Concentration/Value	Unit	Method	Source
Certified value	St,d		1,06	%	GB/T214—20 07 method of determination of total sulfur in coal	
Certified value	Ad		95,62	%		
Certified value	Vd		2,22	%		
Certified value	SiO ₂		52,73	%		
Certified value	Fe ₂ O ₃		5,34	%		
Certified value	CaO		11,81	%		
Certified value	MgO	[1309-48-4]	8,79	%		
Certified value	Al ₂ O ₃		10,93	%		
Certified value	TiO ₂		0,39	%		
Certified value	MnO		0,048	%		
Certified value	K ₂ O		2,39	%		
Certified value	Na ₂ O		1,5	%		
Certified value	P ₂ O ₅		0,083	%		