

Bauxite

Art. ID NCS DC14222
Unit 50 g
Deliverydetails No Dangerous Good /not restricted

Text/Information	Analyte/Parameter	CAS number	Concentration/Value	Unit	Method	Source
	SiO ₂		6,01 ± 0,07	%		
	Al ₂ O ₃		87,5 ± 0,14	%		
	Fe ₂ O ₃		1,61 ± 0,04	%		
	CaO		0,58 ± 0,03	%		
	MgO	[1309-48-4]	0,12 ± 0,02	%		
	K ₂ O		0,087 ± 0,003	%		
	Na ₂ O		0,15 ± 0,02	%		
	TiO ₂		3,14 ± 0,04	%		
	P ₂ O ₅		0,13 ± 0,01	%		
	Loss on Ignition (L.O.I)		0,61 ± 0,03	%		