

Heavy Metals in Wheat Reference Material (low levels) - aluminium, arsenic (total), cadmium, copper, iron, lead, mercury (total), nickel & zinc (all natural/low levels) (TYG047RM)

Art. ID	FAPAS-FCCM32-CCP49RM
Unit	on request
Deliverydetails	No Dangerous Good /not restricted