

## **High Purity Arsenic Certified Reference Material for Arsenic Mass Fraction and Elemental Impurities**

Art. ID	NRC-HIAS-1
Unit	4 g
Deliverydetails	No Dangerous Good

### Description

HIAS-1 is a high purity arsenic metal Certified Reference Material (CRM). A unit of HIAS-1 consists of minimum 4 g of high purity arsenic metal pieces. This material is intended as a primary standard for the determination of mass fraction of arsenic.