

## **Carbon and Sulfur in Tungsten Carbide CRM**

Art. ID AR-307  
Unit 100 g (powder)  
Deliverydetails No Dangerous Good /not restricted

### Description

Carbon and Sulfur in Metals

Text/Information	Analyte/Parameter	CAS number	Concentration/Value	Unit	Method	Source
	Carbon (C)	[7440-44-0]	6,14 ± 0,05	%		
	Sulfur (S)	[7704-34-9]	0,005 ± 0,002	%		