

Quartz

Art. ID SARM-192
Unit 100 g
Deliverydetails No Dangerous Good /not restricted

Text/Information	Analyte/Parameter	CAS number	Concentration/Value	Unit	Method	Source
Certified value / Average value	SiO ₂		98,86	%		
Certified value / Average value	Fe ₂ O ₃		0,51	%		
Certified value / Average value	Al ₂ O ₃		0,03	%		
Certified value / Average value	CaO		0,02	%		