

Tin Calibration Standard, Curie point

Art. ID PE-03190034
Unit each
Deliverydetails ADR Limited Quantity (LQ) / AIR Dangerous Good (DG) /not restricted

Text/Information	Analyte/Parameter	CAS number	Concentration/Value	Unit	Method	Source
	Curie point		232	°C		