

Bauxite

Art. ID NCS DC91017
Unit 50 g
Deliverydetails No Dangerous Good /not restricted

Text/Information	Analyte/Parameter	CAS number	Concentration/Value	Unit	Method	Source
	Al ₂ O ₃		71,14	%		
	CaO		0,75	%		
	Fe ₂ O ₃		2,01	%		
	Ga ₂ O ₃		0,0114	%		
	K ₂ O		0,477	%		
	MgO	[1309-48-4]	0,09	%		
	MnO		0,036	%		
	Na ₂ O		0,022	%		
	P ₂ O ₅		0,221	%		
	Sulfur (S)	[7704-34-9]	0,031	%		
	SiO ₂		3,16	%		
	TiO ₂		3,04	%		
	ZnO		0,0018	%		