

Bauxite

Art. ID NCS DC91019
Unit 50 g
Deliverydetails No Dangerous Good /not restricted

Text/Information	Analyte/Parameter	CAS number	Concentration/Value	Unit	Method	Source
	Al ₂ O ₃		57,15	%		
	CaO		0,089	%		
	Fe ₂ O ₃		16,11	%		
	Ga ₂ O ₃		0,008	%		
	K ₂ O		1	%		
	MgO	[1309-48-4]	0,235	%		
	MnO		0,021	%		
	Na ₂ O		0,31	%		
	P ₂ O ₅		0,077	%		
	Sulfur (S)	[7704-34-9]	0,033	%		
	SiO ₂		6,31	%		
	TiO ₂		2,65	%		
	ZnO		0,0036	%		